Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	43	"5841255" "4384493" "5763969" "6066907"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:04
L2	26	1 and (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:04
L3	9	2 and (indicator indicating display)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:26
L4	1	3 and (damping)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:05
L5	1	3 and (circumferential\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:06
L6	. 4	3 and (elastic\$4 flexure flexible deform\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:15
L7	21	2 and (load pressure strain stress force)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:47
L8	10	7 and (flange)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON .	2007/04/04 14:09
L9	9	8 and (sens\$4 detect\$4 transducer gage gauge cell measur\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR ·	ON	2007/04/04 14:12

						· · · · · · · · · · · · · · · · · · ·
L10	. 4	1 and (input) near3 (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:13
L11	4	10 and (output) near3 (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:14
L12	4	11 and (load pressure strain stress force)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:14
L13		12 and (sens\$4 detect\$4 transducer gage gauge cell measur\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:12
L14		11 and (indicator indicating display)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR _.	ON	2007/04/04 14:12
L15	346	73/774.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:13
L16		15 and (input) near3 (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON .	2007/04/04 14:20
L17	15241	(input) near3 (shaft).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR .	ON	2007/04/04 14:13
L18	10453	17 and (output) near3 (shaft).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:14
L19	1221	18 and (load pressure strain stress force) near3 (measur\$4 cell gage gauge sens\$4 detect\$4 transducer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR _.	ON	2007/04/04 14:48

			-	,	, -	
L20	365	19 and (housing casing cover\$4 frame).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:21
L21	144	20 and (flange)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:15
L22	41	21 and (indicator indicating display)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:15
L23	15	22 and (circumferential\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR _.	ON	2007/04/04 14:15
L24	9	23 and (damping elastic\$4 flexure flexible deform\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:20
L25	472034	(electric) near3 (motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:47
L26		12 and (input) near3 (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:20
L27	15095	25 and (input) near3 (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:21
L28	11727	27 and (output) near3 (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:21
L29	3118	28 and (housing casing cover\$4 frame).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:21

L30	134	29 and (load pressure strain stress force) near3 (measur\$4 cell gage gauge sens\$4 detect\$4 transducer).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR .	ON	2007/04/04 14:22
L31	60	30 and (flange)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:22
L32	19	31 and (indicator indicating display)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:48
L33	28	1 and (electric) near3 (motor)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:47
L34	18	33 and (shaft)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:47
L35	14	34 and (load pressure strain stress force)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:47
L36	11	35 and (measur\$4 cell gage gauge sens\$4 detect\$4 transducer)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:48
L37	4	36 and (indicator indicating display)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/04 14:48

4/4/07 2:51:09 PM Page 4